

00862.022154



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:
KOJI FUKUNAGA
Appl. No.: 09/816,458
Filed: March 26, 2001
For: INFORMATION SIGNAL
PROCESSING APPARATUS
AND METHOD
U.S. Patent No.: 7,177,959 B2
Issued: February 13, 2007)
Examiner: J. Schneider
Group Art Unit: 2182
November 16, 2007)

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
NOV 23 2007
of Correction

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/21/2007 AWONDAF2 00000021 7177959

01 FC:1011

100.00 OP

NOV 29 2007

Patentee's undersigned attorney may be reached in our Costa Mesa, California office by telephone at (714) 540-8700. All correspondence should continue to be directed to our address given below.

Respectfully submitted,


Edward A. Kmett
Attorney for Patentee
Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

FCHS_WS 1468569v1

NOV 29 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 7,177,959 B2

DATED : February 13, 2007

INVENTOR(S) : Fukunaga

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(57) Abstract, Line 6, "instructionis" should read -- instruction is --.

SHEET 7:

FIG. 7, under REGISTER NAME, "CLOCK_STROBE_ARRIVED," should read
-- CLOCK_STROBE_ARRIVED, --.

SHEET 30:

FIG. 30, "LIGTH" should read -- LIGHT --.

COLUMN 11:

Line 11, "relationship" should read -- relationships --.

COLUMN 16:

Line 34, "transferred)" should read -- transferred). --.

COLUMN 22:

Line 7, "have" should read -- has --.

FCHS_WS 1468557v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,177,959 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,177,959 B2

DATED : February 13, 2007

INVENTOR(S) : Fukunaga

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(57) Abstract, Line 6, "instructionis" should read -- instruction is --.

SHEET 7:

FIG. 7, under REGISTER NAME, "CLOCK_STROBE_ARRIVED," should read
-- CLOCK_STROBE_ARRIVED, --.

SHEET 30:

FIG. 30, "LIGTH" should read -- LIGHT --.

COLUMN 11:

Line 11, "relationship" should read -- relationships --.

COLUMN 16:

Line 34, "transferred)" should read -- transferred). --.

COLUMN 22:

Line 7, "have" should read -- has --.

FCHS_WS 1468557v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,177,959 B2

No. of add'l. copies
@ 30¢ per page

NOV 29 2007

